

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG.1




FIG.2




FIG.3








FIG.4



8




FIG. 6

[illegible]

FIG. 7

[illegible]

FIG.8

SUB-BAND		PRECINCT No.								SUB-BIT PLANE		SUB-BIT PLANE		SUB-BIT PLANE		SUB-BIT PLANE		SUB-BIT PLANE	

FIG.9




FIG.10




FIG.11




FIG.12





FIG.13






FIG.14A




FIG.14B

FIG.15

TRANSMISSION LINE CAPACITY (bps)	PICTURE QUALITY LEVEL
1G	LAYER 0
100M	LAYER 2
10M	LAYER 4
8M	LAYER 5
1M	LAYER 7
5.6K	LAYER 10

FIG.16



FIG.17A



51

FIG.17B



52

FIG.17C



53

FIG.17D



54

FIG.18




FIG.19




FIG.20




FIG.21

131

132

130

DISPLAY DEVICE (bps)	THUMBNAIL
DIGITAL CAMERA	CENTRAL TILE LAYER 3
IMAGE VIEWER SOFTWARE	DECOMPOSITION LEVEL 3 LAYER 5
PORTABLE TELEPHONE	DECOMPOSITION LEVEL 5
DIGITAL VIDEO CAMERA	FRAME NUMBER $2N+1$ DECOMPOSITION LEVEL 3
TELEVISION BROADCAST	ALL FRAMES TILES 6,7,10,11 DECOMPOSITION LEVEL 3
HI-VISION BROADCAST	ALL FRAMES DECOMPOSITION LEVEL 3

FIG.22

140



FIG.23A



141

FIG.23B



142

FIG.23C



143

FIG.23D



144

FIG.24




FIG.25




FIG.26




FIG.27

